

PART C

Assembly Drawings: (Part drawings shall be given)1. Plummer block (Pedestal Bearing)


- 2. Rams Bottom Safety Valve
- 3. I.C. Engine connecting rod
- 4. Screw jack (Bottle type)5. Tailstock of lathe
- 6. Machine vice
- 7. Lathe square tool post (15 Hours)




Dataile of a Konne Last.




Details of a Machine Vice



Details of a Tailstock



Details of a Ramsbotton: Safety Valve Fig. 22.14



Details of a Petrol Engine Connecting Rod

